







July 2026 Operations Department Report



**Service Line Relocate
- Crotty - Rancho
Calaveras**



**1 1/4 inch line Repair -
Acorn - West Point**



**1-inch Corp - Pine Drive -
Arnold**



**1-inch Corp - Pine
Drive - Arnold**





**1-inch Poly - 5th
Green - Arnold**



RP Backflow Prevention Device - Replacement - Big Trees Shopping Center





**RP Backflow Prevention
Device - Replacement - Big
Trees Shopping Center**



**RP Backflow Prevention
Device - Replacement - Big
Trees Shopping Center**



**RP Backflow Prevention
Device - Replacement - Big
Trees Shopping Center**



**RP Backflow Prevention
Device - Replacement - Big
Trees Shopping Center**



**RP Backflow Prevention
Device - Replacement - Big
Trees Shopping Center**



**Ebbetts Pass Crew - Fire
Hydrant Surge Relief -
Rebuild**





**Distribution Crew
Maintenance - Ebbetts Pass**



Distribution Crew Maintenance - Ebbetts Pass




6-Inch Main Break
- Sheep Ranch



**6-Inch Main Break
- Sheep Ranch**



**6-Inch Main Break
- Sheep Ranch**



Mechs - Influent Check Valve Rebuilds - Jenny Lind WTP



**Construction - Site work and Pad Construction -
SAF pre-treatment unit - Copper Reclaim**



**Construction - Site work and Pad Construction -
SAF pre-treatment unit - Copper Reclaim**



**Construction - Site work and Pad Construction -
SAF pre-treatment unit - Copper Reclaim**





**Construction - Site work and Pad Construction -
SAF pre-treatment unit - Copper Reclaim**





**Construction - Hydrant
Replacement Recon - Heney
- Rancho Calaveras**





**Electrical - Troubleshoot the Radio and HMI Conflict -
Wilseyville Lift Station**



**Electrical - Troubleshoot
Aeration fail at La Contenta
WWTP - Replaced blown
control transformer fuse and
diag'd bad coil**



Electrical - Troubleshoot and repaired BW function - Filter #1 - Copper Cove WTP



Thank You