



# February and March 2026 Operations Department Report



**1-inch Corp Stop -  
Fairway - Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**




**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**




**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**Leak at PRV 30 on Thunderbolt -  
Ebbetts Pass**



**PG&E Prep - Influent Feed Line - Tunnel Tap - Hunters WTP**



**PG&E Prep - Influent Feed Line -  
Tunnel Tap - Hunters WTP**



**PG&E Prep - Influent Feed Line -  
Tunnel Tap - Hunters WTP**



**PG&E Prep - Influent Feed Line -  
Tunnel Tap - Hunters WTP**



**PG&E Prep - Influent Feed Line -  
Tunnel Tap - Hunters WTP**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Lilac Drive Service Line Repair -  
Ebbetts Pass**



**Fire Hydrant Replacement - Manual Road - Arnold**




**Fixed a leak on the Reclaimed Water line - Vallecito  
Installing an inline Valve in Big Trees Village**





**Troubleshoot and Repaired Aerator  
#2 - Copper Cove WWTP**



**Used the Bucket Truck to Re-Aim the telemetry radio antenna from the West Point WWTP to the new septage receiving building. Used the bucket truck. Corrected a latency issue.**




**Corrected Failure to Alternate Pumps in the PLC at the Huckleberry Lift Station - La Contenta**



**Corrected trending issues on the new SCADA computers - cleaned up old equipment - Copper Cove WTP**



**Replaced old panel backboards -  
La Contenta WWTP**





**Added a new level transducer to the new Copper Cove B-Tank #2**




**Added a new level transducer to the new Copper Cove B-Tank #2**




**Troubleshoot Lake Pump #2 Failure -  
Copper Cove RWPS**



**Troubleshoot and corrected BWR Pump #1 at the JLWTP trip issue**



**Troubleshoot and corrected High-level callout issue - Lift Station 10 - Copper**



**Met with Divers at the Copper Cove RWPS to inspect wiring and confirm Pump 2 failure**



**Met with Divers at the Copper Cove RWPS to inspect wiring and confirm Pump 2 failure**



**De-Ragged Pumps at Lift Station 10  
- Poker Flat**



**De-Ragged Pumps at Lift Station 10  
- Poker Flat**



**De-Ragged Pumps at Lift Station 10  
- Poker Flat**




**Began Filter Rehabilitation Project -  
Copper Cove WTP**



**Began Filter Rehabilitation Project -  
Copper Cove WTP**



**UV System Maintenance - Copper Cove Reclamation Plant**



**Thank You**