

CCWD FIELD OPERATIONS


January 2025 Department Report February 12th, 2025




2
















8













4



SILVER RAPIDS AND HARTVICKSON- RANCHO CALAVERAS

SERVICE LINE REPLACEMENT – DALEE – RANCHO 16 CALAVERAS 2/13/2025

SERVICE LINE REPLACEMENT – DALEE – RANG




SERVICE LINE REPLACEMENT – DALEE – RANCHO 17 CALAVERAS 2/13/2025






NEW SERVICE INSTALLATION – HENEY – RANCHO¹⁸ CALAVERAS





NEW SERVICE INSTALLATION – HENEY – RANCHO 19 CALAVERAS













SERVICE LINE REPAIR - FAIRWAY DR. EBBETTS PASS






SERVICE LINE REPAIR - FAIRWAY DR. EBBETTS PASS

2/13/2025



PRV 51 - MAINTENANCE EBBETTS PASS

2/13/2025



PRV 51 - MAINTENANCE EBBETTS PASS







LIFT STATION CLEANUP & REPAIR – WEST POINT



PROTECT YOUR PIPING! – EBBETTS PASS 29




REPLACING AGED FUELING EQPT – WEST POINT






REPLACEMENT OF BURNED METER & BOX – WEST 31 POINT 2/13/2025






REPLACEMENT OF BURNED METER & BOX – WEST 32 POINT 2/13/2025

WARMWOOD LIFT STATION TRANSDUCER & PLC REPAIR 2/13/20







34 B-TANK PRESSURE SYSTEM VOLTAGE CHECK - 2/13/2025 **RANCHO CALAVERAS**







2/13/2025





BEAR CREEK DIVERSION ACCESS CLEANUP – WEST POINT





BEAR CREEK DIVERSION ACCESS CLEANUP – WEST POINT

38



MAIN CORP YARD CLEAN UP - SAN ANDREAS

2/13/202



MAIN CORP YARD CLEAN UP – SAN ANDREAS

2/13/2025



EXTENDING THE ROTORK AIR VALVE ACTUATOR TO FACILITATE OPERATION - VALLECITO





EXTENDING THE ROTORK AIR VALVE ACTUATOR TO FACILITATE OPERATION - VALLECITO

