


CCWD FIELD OPERATIONS

May 2023 Department Report

June 14, 2023



FIRE FLOW TESTING – RANCHO CALAVERAS



FIRE FLOW TESTING – RANCHO CALAVERAS



FIRE FLOW TESTING – RANCHO CALAVERAS



**APACHE DRIVE 1" FLARED POLY – EBBETTS
PASS**



HILLCREST – HATHAWAY PINES – EBBETTS PASS



CORP STOP INSTALL – 5TH GREEN – EBBETTS PASS



LOCATING – ACORN WAY – WEST POINT



ADDING PROTECTION TO THE WAREHOUSE – WEST POINT



ADDING PROTECTION TO THE WAREHOUSE – WEST POINT



LEAK REPAIR – FAY & BARBARA – WEST POINT ¹¹

6/14/2023



2ND FILTER ADDITION – WEST POINT

12

6/14/2023



REPLACING FUEL LINE ON THE CUT OFF SAW 13-

VALLECITO

6/14/2023



CONDUIT TRENCHING – VALLECITO



POTHOLING AND INSTALLING EFF LINE - VALLECITO



REPAIRING CULVERT AND INSTALLING WATER LINE - VALLECITO



FORMS AND CONCRETE FOR TRASH RACK – VALLECITO



FORMS AND CONCRETE FOR TRASH RACK – VALLECITO



TRASH RACK INSTALL – VALLECITO



FIRE CREW CLEAN UP – VALLECITO



FIRE CREW CLEAN UP – VALLECITO

21

6/14/2023



FIRE CREW CLEAN UP – VALLECITO

22

6/14/2023



FIRE CREW CLEAN UP – FOREST MEADOWS

23

6/14/2023



FIRE CREW CLEAN UP – FOREST MEADOWS

24

6/14/2023



FIRE CREW CLEAN UP – FOREST MEADOWS



QUAD REPAIR WORK - MECHANICAL



HYDRAULIC CYLINDER REPLACEMENT VEH 736 - MECHANICAL



PULLED SOUTHWORTH AERATOR & CHECKED OPERATION - MECHANICAL

28

6/14/2023



BIG TREES TANK 4 FIRE



BIG TREES TANK 4 FIRE

30

6/14/2023



BIG TREES TANK 4 FIRE



BIG TREES TANK 4 FIRE



RELOCATION OF TELEMETRY ANTENNA



RELOCATION OF TELEMETRY ANTENNA

34

6/14/2023



THANK YOU -
QUESTIONS