

CCWD FIELD OPERATIONS

July 2024 Department Report

August 14, 2024

Active Service Request This Month


25

Last update: a minute ago


Open Work Orders This Month

11


Last update: a minute ago




Overview



Last update: a minute ago




Last update: a minute ago



Service Requests by Category

Last update: a minute ago



Crew Names

Last update: a minute ago

Service Request Totals by Month

Service Requests By Category This Year

Leak Check By Month

Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

OPERATIONAL DASHBOARD

Active Service Request This Month


25

Last update: 3 minutes ago


Open Work Orders This Month

11


Last update: 3 minutes ago




SR - Jenny Lind



Last update: 3 minutes ago




Last update: 3 minutes ago



Service Requests by Category This Year

Last update: 3 minutes ago



Open Work Orders This Month By Crew

Last update: 3 minutes ago

Service Request Totals by Month

Service Requests By Category This Year

Leak Check By Month

Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

OPERATIONAL DASHBOARD

Active Service Request This Month


25

Last update: 4 minutes ago


Open Work Orders This Month

11


Last update: 4 minutes ago



Last update: 4 minutes ago



Last update: 4 minutes ago




SR - Jenny Lind



Leak Check By Month

Last update: 4 minutes ago



Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

Last update: 4 minutes ago

OPERATIONAL DASHBOARD

Active Service Request This Month


25

Last update: 9 minutes ago


Open Work Orders This Month

11


Last update: 9 minutes ago




SR - Ebbitts Pass



Last update: 9 minutes ago




Last update: 9 minutes ago



Service Requests by Category This Year

Last update: 9 minutes ago



Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

Last update: 9 minutes ago

OPERATIONAL DASHBOARD

Active Service Request This Month


25

Last update: 10 minutes ago


Open Work Orders This Month

11



Last update: 10 minutes ago



Last update: 10 minutes ago




Last update: 10 minutes ago



Service Requests by Category This Year

Last update: 10 minutes ago



Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

Last update: 10 minutes ago

OPERATIONAL DASHBOARD

Active Service Request This Month

25


Last update: 10 minutes ago

Open Work Orders This Month

11


Last update: 10 minutes ago

USA Tickets This Year By Group




Last update: 10 minutes ago


USA Tickets



Last update: 10 minutes ago




Last update: 10 minutes ago



Service Requests by Category This Year

Last update: 10 minutes ago



Work Orders By Type

Last update: 10 minutes ago

Service Request Totals by Month

Service Requests By Category This Year


Leak Check By Month

Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

OPERATIONAL DASHBOARD




Last update: 12 minutes ago

Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type


OPERATIONAL DASHBOARD



Last update: 13 minutes ago

- Work Orders This Year by Crew
- Open Work Orders This Month By Crew
- Work Orders This Year by Type

OPERATIONAL DASHBOARD



Service Requests by Category


Last update: 36 minutes ago

Service Request Totals by Month

Service Requests By Category This Year

Leak Check By Month

OPERATIONAL DASHBOARD



OPERATIONAL DASHBOARD



CORPORATION STOP & SERVICE REPLACEMENT WESTHILL – RANCHO CALAVERAS



CORPORATION STOP & SERVICE REPLACEMENT WESTHILL – RANCHO CALAVERAS

13

8/14/2024



CORPORATION STOP & SERVICE REPLACEMENT WESTHILL – RANCHO CALAVERAS



SERVICE LINE REPAIR – BALDWIN AT KIRBY ¹⁵ NEW SHORING BOX IN ACTION

8/14/2024



ARV REPAIR – EBBETTS PASS – PIPELINE FEEDS B.T. STATE PARK



ARV REPAIR – EBBETTS PASS – PIPELINE FEEDS B.T. STATE PARK



EBBETTS PASS PRV INSPECTIONS & MAINTENANCE



EBBETTS PASS PRV INSPECTIONS & MAINTENANCE



EBBETTS PASS PRV INSPECTIONS & MAINTENANCE



WATER QUALITY FLUSHING – EBBETTS PASS



CONSTRUCTION CREW – INDIAN ROCK WWTP ROAD

22
8/14/2024



CONSTRUCTION CREW – INDIAN ROCK WWTP ROAD

23
8/14/2024



CONSTRUCTION CREW – INDIAN ROCK WWTP ROAD

24
8/14/2024



CONSTRUCTION CREW – INDIAN ROCK WWTP ROAD

25
8/14/2024



CONSTRUCTION CREW – CLEANING ACCESS ROAD TO B.T. S.P WATER LINE & RAISING VALVE BOXES



MECHANICAL CREW – REPLACING THE LARKSPUR P.S. CLA-VAL



ELECTRICAL – REMOVED OLD COPPER OZONE GENERATOR – INSTALLED NEW





ELECTRICAL – REMOVED OLD COPPER OZONE GENERATOR – INSTALLED NEW



ELECTRICAL – TOSHIBA TRAINING AND STARTUP OF THE NEW OZONE UPS – COPPER COVE WTP

30

8/14/2024



ELECTRICAL – REMOTE SCADA WORK TO CC LIFT STATION 7 – ADDED TIME DELAY TELEMETRY ALARM




ELECTRICAL – REPLACED VIPR COMMS RADIO AT LIFT STATION 7



ELECTRICAL – PG&E TRANSFORMER ISSUES DESTROYED B TANK COMMS

8/14/2024

33



ELECTRICAL – PG&E TRANSFORMER ISSUES DESTROYED B TANK COMMS



COLLECTIONS & ELECTRICAL – VALLECITO LIFT STATION PUMP 1 FAILURE



THANK YOU – QUESTIONS?